







UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.						
		W A D 9 8 0 7 3 8 5 4 6 9 3 0 0 5 1		6 9 3 0 0 5 1										
GENERATOR	3. Generator's Name and Mailing Address ALASKAN COPPER WORKS 3200 Sixth Avenue South Seattle WA 98134						A. State Manifest Document Number							
	4. Generator's Phone (206) 623-5801						B. State Generator's ID							
	5. Transporter 1 Company Name C.K.C., Incorporated						C. State Transporter's ID 410 657							
	6. US EPA ID Number C A D 9 8 0 5 8 4 5 1 0						D. Transporter's Phone (408) 627-2595							
	7. Transporter 2 Company Name						E. State Transporter's ID							
	8. US EPA ID Number						F. Transporter's Phone							
	9. Designated Facility Name and Site Address World Resources Company 8113 West Sherman Street Phoenix, Arizona 85043						G. State Facility's ID							
	10. US EPA ID Number A Z D 9 8 0 7 3 5 5 0 0						H. Facility's Phone (602) 233-9166							
	11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)						12. Containers		13. Total Quantity		14. Unit Wt/Vol		1. Waste No.	
	a. <div style="border: 1px solid black; padding: 2px;">HM</div> RQ, Hazardous waste, solid, n.o.s., (F006), 9, NA3077, III						0 0 3 C F		0 4 0 3 4		P		F006	
b. RQ, Hazardous waste, solid, n.o.s., (F006), 9, NA3077, III						0 0 3 C F		0 4 0 3 4		P		F006		
c.														
d.														
J. Additional Descriptions for Materials Listed Above						K. Handling Codes for Wastes Listed Above <div style="font-size: 2em; text-align: center;">01</div>								
15. Special Handling Instructions and Additional Information *** 24 HOUR EMERGENCY RESPONSE: 1-(800) 424-9300 CHEMTREC *** WEAR GOGGLES AND GLOVES														
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.														
Printed/Typed Name GERALD A. THOMPSON						Signature 		Month Day Year 10 9 3 0 9 3						
TRANSPORTER	17. Transporter 1 Acknowledgement of Receipt of Materials													
	Printed/Typed Name Mike Portney						Signature 		Month Day Year 10 9 3 0 9 3					
	18. Transporter 2 Acknowledgement of Receipt of Materials													
Printed/Typed Name						Signature		Month Day Year						
19. Discrepancy Indication Space														
FACILITY	20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.													
	Printed/Typed Name Natividad Diaz						Signature 		Month Day Year 1 10 0 7 9 3					

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. W 4 0 9 8 0 7 3 8 5 4 6 9 3 0 0 5		Manifest Document No. 9 3 0 0 5		2. Page 1 of 1		Information in the shaded areas is not required by Federal law.	
		3. Generator's Name and Mailing Address ALASKAN COPPER WORKS 3200 Sixth Avenue South Seattle WA 98134		6. US EPA ID Number C A D 9 8 0 5 8 4 5 1 0		A. State Manifest Document Number		B. State Generator's ID	
4. Generator's Phone (206) 623-5801		7. Transporter 2 Company Name		8. US EPA ID Number		C. State Transporter's ID 410 687		D. Transporter's Phone (408) 627-2595	
5. Transporter 1 Company Name C.K.C., Incorporated		9. Designated Facility Name and Site Address World Resources Company 8113 West Sherman Street Phoenix, Arizona 85043		10. US EPA ID Number A 2 0 9 8 0 7 3 8 5 4 6		E. State Transporter's ID		F. Transporter's Phone	
						G. State Facility's ID		H. Facility's Phone (602) 233-9166	
11. US DOT Description (Including Proper Shipping Name, Hazard Class and ID Number)		12. Containers		13. Total Quantity		14. Unit Wt/Vol		1. Waste No.	
a. <input type="checkbox"/> HM RC, Hazardous waste, solid, n.o.s., (F006), 9, NA3077, III		No. Type 0 0 3 C F		0 4 0 3 4		P		F006	
b. <input type="checkbox"/>									
c. <input type="checkbox"/>									
d. <input type="checkbox"/>									
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above							
15. Special Handling Instructions and Additional Information 24 HOUR EMERGENCY RESPONSE: 1-(800) 424-9300 CHENTREC *** WEAR GOGGLES AND GLOVES									
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.									
Printed/Typed Name GERALD A. THOMPSON					Signature 			Month Day Year 8 1 1993	
17. Transporter 1 Acknowledgement of Receipt of Materials									
Printed/Typed Name Mike Portney					Signature 			Month Day Year 8 1 1993	
18. Transporter 2 Acknowledgement of Receipt of Materials									
Printed/Typed Name					Signature			Month Day Year	
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.									
Printed/Typed Name					Signature			Month Day Year	

MATERIAL IDENTIFICATION

DOT SHIPPING NAME: Hazardous Waste Solid N.O.S.
DOT HAZARD CLASS: ORM-E
UN OR NA NUMBER: NA 9189



DOT EMERGENCY RESPONSE GUIDE 31

POTENTIAL HAZARDS

FIRE OR EXPLOSION

Some of these materials may burn, but none of them ignites readily.

HEALTH HAZARDS

Contact may cause burns to skin and eyes.

Fire may produce irritating or poisonous gases.

Runoff from fire control or dilution water may cause pollution.

EMERGENCY ACTION

Keep unnecessary people away.

Isolate hazard area and deny entry.

Self-contained breathing apparatus (SCBA) and structural firefighter's protective clothing will provide limited protection.

CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE. If water pollution occurs, notify the appropriate authorities.

FIRE

Small Fires: Dry chemical, CO2, Halon, water spray or standard foam.

Large Fires: Water spray, fog or standard foam is recommended.

Move container from fire area if you can do it without risk.

Do not scatter spilled material with high-pressure water streams.

Dike fire control water for later disposal.

SPILL OR LEAK

Stop leak if you can do it without risk.

Small Dry Spills: With clean shovel place material into clean, dry container and cover, move containers from spill area.

Small Spills: Take up with sand or other noncombustible absorbent material and place into containers for later disposal.

Large Spills: Dike far ahead of liquid spill for later disposal.

Cover powder spill with plastic sheet or tarp to minimizing spreading.

FIRST AID

In case of contact with material, immediately flush eyes with running water for at least 15 minutes.

Wash skin with soap and water.

Remove and isolate contaminated clothing and shoes at the site.

NOTE: If this response guide is used as an attachment for shipping documents, enter shipping manifest number in block below.

93005

(shipping manifest number)

MSDS-1

Material Safety Data Sheet

Recycler's Facility Name and Site Address:

World Resources Company

8113 West Sherman Street
Phoenix, Arizona 85043

Telephone Number: 1-602-233-9166

Issued: 8/7/90

Revised: 2/6/91

Revised: 2/16/93

Call CHEMTREC only in the event
of emergencies during shipping that
involve a spill, leak, fire, or accident

For Emergencies During

Shipping Call:

CHEMTREC

Day or Night

800-424-9300

Outside Continental U.S. Call:

202-483-7616 Collect

All calls are recorded.

Section 1

PRODUCT - MATERIAL IDENTIFICATION

Generic Name: Electroplating/Metal-Finishing Wastewater Treatment Sludge

Environmental Protection Agency (EPA) Waste Classification: F006

Chemical Family: Metallic (Hydroxide) Precipitates

Synonym: Non-ferrous Metal Hydroxide Filter Cake

DOT Shipping Name: Hazardous waste, solid, n.o.s.

DOT Hazard Class: 9

DOT Identification Number: NA 3077

DOT Packing Group: III

DOT Emergency Response Guide 31 Applies

Section 2

HAZARDOUS INGREDIENTS

Ingredient:	CAS Number:	Content %:	ACGIH-TLV	Toxicology: (rat, oral)
Copper Hydroxide	20427-59-2	0-30	1.0 mg/m ³ (Dust)	LD-50 1,000 mg/kg
Nickel Hydroxide	12054-48-7	0-15	1.0 mg/m ³ (Dust)	LD-50 1,500 mg/kg
Calcium Hydroxide	1305-62-0	0-15	5.0 mg/m ³ (Dust)	LD-50 7,340 mg/kg
Diatomaceous Earth	68855-54-9	0-10	6.0 mg/m ³ (Dust)	LD-50 3,160 mg/kg

Section 3

PHYSICAL AND REACTIVITY DATA

Description: Solid, Clay-like Clumps,
Gray/Green to Brown,
Water Content 30-80%

Specific Gravity: 1 to 1.4

Solubility: Insoluble in water

Density: 64 to 90 lbs/cu/ft

Incompatible Reactivity: None Known

Vapor Pressure: Insignificant

Stability: Avoid contact with acids

Polymerization: Will not occur

Boiling Point: Above 2600°C

Melting Point: Above 1800°C

pH: 7.0 to 10.0

Odor: Nil

Section 4

FIRE AND EXPLOSION DATA

Flashpoint: Nonflammable

Special Firefighting Procedures: None


Product Decomposition: (Due to Fire or Explosion): None

Oxidation: Non-oxidizing

Explosive: Non-explosive

NFPA

Fire Diamond



Section 5

TOXICITY

Listed Carcinogen component: Nickel

Toxicology: See Sec. 2 (Nickel Hydroxide)

Route of Entry: Inhalation and Ingestion

Section 6

HEALTH EFFECTS AND FIRST AID

Inhalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms.

Ingestion: Rare in industry. Induce vomiting (do not induce vomiting or give a liquid to an unconscious person) and call a physician.

Eyes: Dust may irritate eyes. Wash with copious amounts of water for 15 minutes, if effects persist, call a physician.

Skin: Dust may irritate skin, causing forms of eczema. Wash with soap and water.

Long-Term Effects: Chronic overexposure may affect the following target organs or body systems—blood, digestive, respiratory, lungs, liver, kidneys and skin.

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent kidney damage and metal-sensitive skin or skin lesions.

Section 7

PRECAUTIONS FOR SAFE HANDLING

Handling: Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment be used by personnel who will come in contact with the material. The equipment should include eye protection, respirator and gloves.

Storage: Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled to avoid inhalation or ingestion. Store in a dry area under cover from rain.

Spills: Cleaning procedures should not create excessive dust. Vacuum when possible. Package material and send to World Resources Company at above address.

Section 8

CONTROL MEASURES

Respiratory Protection: NIOSH-MSHA approved respirators as required.

Other Protective Equipment: Coveralls are recommended, but not required.

Eye Protection: Safety Glasses recommended.

Hand Protection: Gloves recommended.

Section 9

GENERATORS VERIFICATION

This MSDS is provided solely for informational purposes and no warranty or responsibility is extended even though reasonable precautions have been taken in the preparation of the data contained for this recyclable material. To the best of my knowledge this MSDS describes the recyclable material listed on the attached Manifest Number: 93005 Telephone: (206) 623 5806 Date: 9/30/93

Company Name and Address: Alaskan Copper Works
3200 Sixth Avenue South Seattle, WA 98134

Signature:

AZF-WRC 2/93

NOTICE

TO: World Resources Company
8113 West Sherman Street
Phoenix, Arizona 85043

FROM: ALASKAN COPPER WORKS
(Company Name)
628 S. HANFORD ST. SEATTLE WA 98134
(Address)

SUBJECT: Land Disposal Restriction Notice


Manifest Number: 93005

Date of Shipment: SEPTEMBER 30 1993

This shipment of material, which is being provided for recycling, is subject to the land disposal restrictions of 40 CFR, Part 268, Subpart D or the prohibitions specified in §268.32 or RCRA §3004(d). The applicable Land Disposal Restriction Information is provided in accordance with 40 CFR §268.7 and is shown below:

EPA Material Number	Regulated Constituent	Subcategory	Treatability Group	Treatment Standards	
				CFR Reference	Prohibition Level
F006	N/A	N/A	Nonwastewater	40 CFR §268.41 40 CFR §268.43	---

NOTE: See attached sheet for instructions.

By: 
Title: ENVIRO. ASST.